

Summary of Boarding and Attempted Boarding Incidents in the Singapore Strait (caa 1 Dec 2022)

Number of Incidents & Vessel Types





Key Observations and Assessments

- Of the seven new incidents, <u>five</u> occurred in Phillip Channel, and <u>two</u> occurred in the Westbound Lane of the Traffic Separation Scheme (TSS), within the Singapore Strait. Of note, the <u>five</u> incidents in Phillip Channel during Nov 2022, is the highest number of incidents in Phillip Channel recorded within a month since Jan 2022.
- In all the incidents, the perpetrators were not armed, and there was no confrontation and injury reported. Of note, most of the incidents reported items stolen.
- <u>Two</u> incidents on 21 Nov 2022 occurred within 2 hours and 0.5nm apart from each other; assessed likely to be conducted by the same group of perpetrators due to similar group size (3-14 perpetrators), proximity of location, and time between incidents.

Modus Operandi: Remains Largely Consistent With Petty Crime

- Based on the incident reports this year, in most cases, the perpetrators avoided confrontation, and fled immediately upon being sighted by crew.
- Perpetrators are usually unarmed, and in group of average 4-6 pax, and they use small boats to target slow-moving vessels (7-12 knots) with low freeboard.

ı	Cargo Ships, Bulk Carriers & Tankers	Tugs & Barges
ſ	• May be armed and confrontational e.g., small arms, knives, and steel bars	Usually unarmed
	(Out of 52 incidents since Jan 2022, 13 reported armed and 3 reported with	Usually target scrap metal
	confrontation)	 Could be targeted in both
	Usually target ship's engine parts and stores	daylight and hrs of darkness
	Same group of perpetrators may target few vessels in succession, in same	
ı	night	

Recommended Actions for All Transiting Vessels

- Remain vigilant, particularly when transiting the areas of concern in the Phillip Channel, and off Bintan and Batam
- Adopt Ship Protection Measures recommended in the Regional Guide 2 to Counter Piracy and Armed Robbery Against Ships in Asia, e.g., (1) turn on weather deck lighting around the accommodation block and rear facing lighting on the poop deck, (2) maintain an all-round lookout at an elevated position with focus on suspicious small craft(s) approaching or in proximity to the ship's aft, and (3) sound ship's alarm when suspicious small craft(s) sighted
- To avoid successive attempts by the same group of perpetrators, shippers will need to participate in Voluntary Community Reporting as
 depicted in 4th Edition MARSEC Charts Q6112 and Q6113; upon sighting of suspicious activities, immediately report to local authorities
 and inform the IFC